
Preliminary Hand- Held Air Monitoring Locations | ITC Deer Park Tank Fire

Reading Date

3/31/2019 2:00:00 AM to 3/31/2019 3:00:00 AM



Recent Benzene Detections

Location Category	Reading Date	Concentration
Division E	3/31/2019 02:48:12	0.53 ppm
	3/31/2019 02:35:17	0.75 ppm
	3/31/2019 02:31:37	0.98 ppm
	3/31/2019 02:28:10	0.04 ppm
	3/31/2019 02:27:53	0.21 ppm
	3/31/2019 02:20:06	0.27 ppm
	3/31/2019 02:18:27	0.60 ppm
	3/31/2019 02:17:57	0.30 ppm
	3/31/2019 02:16:09	0.90 ppm
	3/31/2019 02:13:53	0.30 ppm
	3/31/2019 02:10:33	0.59 ppm
	3/31/2019 02:10:04	0.28 ppm
	3/31/2019 02:06:49	0.09 ppm
Impacted Tank Farm	3/31/2019 02:04:22	0.83 ppm
Industrial Area	3/31/2019 02:30:07	0.35 ppm
	3/31/2019 02:27:52	1.40 ppm
	3/31/2019 02:21:22	0.10 ppm
	3/31/2019 02:19:48	12.55 ppm
	3/31/2019 02:04:14	2.13 ppm
	3/31/2019 02:00:32	1.33 ppm

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis. It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only

Reading Date 3/31/2019 2:00:00 AM to 3/31/2019 3:00:00 AM

Benzene Action Level Concentration (ppm) >=1 >=2

PRELIMINARY

Recent Benzene Detections Greater than 1.00 ppm

Reading Date	Location Category	GPS	Google Maps URL	Concentration
3/31/2019 02:27:52	Industrial Area	29.7218540,-95.1040370	https://www.google.com/maps/search/?api=1&query=29.7218540,-95.1040370	1.40 ppm
3/31/2019 02:19:48	Industrial Area	29.7216290,-95.0967860	https://www.google.com/maps/search/?api=1&query=29.7216290,-95.0967860	12.55 ppm
3/31/2019 02:04:14	Industrial Area	29.7187880,-95.0932280	https://www.google.com/maps/search/?api=1&query=29.7187880,-95.0932280	2.13 ppm
3/31/2019 02:00:32	Industrial Area	29.7187890,-95.0932240	https://www.google.com/maps/search/?api=1&query=29.7187890,-95.0932240	1.33 ppm